



1. WIRING DIAGRAMS

Screw terminals, overview




Terminal assignment

Standard IP Transducer




Loop Input
4 - 20 mA



Position Feedback




2 SPDT Mechanical Switches
Camden CSM30520D




2 SPDT Magnetic sensors
Hamlin Reed 9145



2 Inductive Sensors NAMUR
P+F NJ2-V3-N



Resistive Output
0 - 10K ohm
0 - 1K ohm



Current Output

